

# Dairy Cattle Barn

Herrick Archives Number H 301

## A. IDENTIFICATION & LOCATION

### 1. Name

1.1 Never officially named by Board of Trustees action.

1.2 Alternate names noted:

Dairy Barn

Cattle Barn

### 2. Location

2.1 Located on the site of Building 022. See report for Building 022.

See Addendum No. 1.

### 3. General Description

3.1 Type of construction:

Frame structure on concrete and brick foundation (McC 4: 275).

3.2 Area of building was 14,342 sq. ft. (McC 4: 9A).

3.3 Volume of building was 276,203 cu. ft. (McC 4: 9A). Note: This cubage is identical with that of Building 022, which replaced it. It seems unlikely that the two buildings would be identical in volume, and it appears probable that McCracken erred. The error, however, is not large.

## B. PLANNING & CONSTRUCTION

1. On February 17, 1922 the Board of Trustees approved the plans and related documents prepared by Joseph N. Bradford and authorized the solicitation of bids by contractors,

2. Bids were received on March 27, 1922 (T).

3. On April 5, 1922 the Board of Trustees awarded contracts to the following contractors:

General: E. Elford

Electrical: E. H. Cobb

Plumbing & drainage: Huffman-Wolfe Co.

4. Beginning of work:

Work was started October 2, 1922 (A)

5. Completion and occupancy:

Building accepted from the contractor by Board of Trustees on October 20, 1922.

### C. COST

Cost reported at \$32, 086. 28 (B & McC 4: 9A).

### D. DEMOLITION

This barn burned on December 13, 1943 (T 1/3/44).

### E. PHOTOGRAPHS

1. In Photoarchives:

- X 1244--building on far left. Photograph taken from northeast.
- X 1344—from the west.
- X 1343—from the west.

2. Other:

McC 4: 2 5 6" Follow ing p. 256 are two photographs. In each case. Building H 301 appears in the left margin.

John H. Herrick

August 25, 1972

### ADDENDUM NO. 1

For indexing purposes, this building has been given the same address as its successor (022), namely 1973 Plumb Hall Court.

John H. Herrick

February 4, 1976